## **AVIATION ENTERPRISES**

## WING EXTENSION SERVICE LETTER

**NOVEMBER 6, 2000** 

**AE 01-11-00** 

SUBJECT: WING EXTENSIONS

AIRCRAFT APPLICABILITY: All Cessna 337 Skymasters with Aviation Enterprises Wing Tip Extensions STC SA02055AT and Lightning wing tips STC SA0194AT plus Skymasters Serial #s P337-0350 and 33701448 (with modified Flint Tip Tanks and Lightning Wing Tips)

## **REASON FOR LETTER:**

As part of a continuing program of improving the safety, reliability, and utility of Skymasters with the wing extensions installed, a series of investigations are ongoing. As part of this safety program, we are sending a placard to be installed on the instrument panel in full view of the Pilot.

Part Number: Plac-WE-1

Install on the instrument panel in full view of the Pilot

While this aircraft is equipped with wing tip extensions.

- Maximum Airspeed for turbulence penetration is limited to 140 KLAS (maneuver speed, Va, @ 5120 lbs) Refer to applicable AFMS or POH for maneuver speeds at reduced gross weights.
- Maximum Zero Fuel Weight limited to 4220 lb
  (all weight above 4220 lb must be wing fuel weight)

  CAUTION

Landing on unpaved runways is not recommended

## CONFIRMATION OF PLACARD INSTALLATION;

Please send confirmation as to the date of installation of this placard.

To: Aviation Enterprises

Fax: 615-865-1802

E-Mail: owen.bell@juno.com

